

ANNEXURE-3

FIELD PHOTOGRAPHS



Plate-1: HTL at Embankment construction along the canal at Puthenthura
(Location: 76° 32' 4.64" E 8° 58' 6.80" N, Neendakara Panchayat,
Village:Neendakara)



Plate-2: Mangrove area at Ayiramthengu (Location: 76° 28' 41.91" E 9° 7' 13.809"
N, Clappana Panchayath, Village: Clappana)



Plate-3: Mangrove patch at Pandarathuruthu (Location: $76^{\circ} 30' 56.4''E$ $9^{\circ} 1' 46.23''N$, Alappad Panchayat, Village: Alappad)



Plate-4: HTL at Vellanathuruthu Beach (Location: $76^{\circ} 31' 7.69''E$ $9^{\circ} 1' 8.65''N$, Panmana Panchayat, Village: Panmana)



Plate-5: Mangrove area found to be removed at Neelashwaram thoppu, Thuruthu (Location: 76° 32' 55.19" E 8° 56' 35.48"N, Neendakara Panchayat, Village: Neendakara)



Plate-6: Mangrove area found to be removed at Neelashwaramthoppu, Thuruthu (Location: 76°32'56.35"E 8°56'41.17", Neendakara Panchayat, Village: Neendakara)



Plate-7: Mangroves at Dalavappuram (Location: 76°32'56.26"E 8°57'4.88"N, Neendakara Panchayat, Village: Neendakara)



Plate-8: Mangroves Near IPC Pentecostal Church at Chavara (Location: 76° 32' 52.55" E 8° 58' 14.50", Chavara Panchayat, Village: Chavara)



Plate-9: Mangroves at Mundrothurthu (Location: 76° 36' 25.91" E 8°59'18.96"N, Mundrothuruthu Panchayat, Village: Mundrothurthu)



Plate 10: Mangrove area found to be removed at Kavanad bridge (Location: 76°33'43.24"E 8°55'24.75", Kollam Corporation, Village: Thrikkadavoor)