

# **ANNEXURE-3**

## **FIELD PHOTOGRAPHS**



Plate-1: HTL at Vallikkunnu Beach (Location: 75° 50' 17.98" E 11° 5' 30.40" N, Vallikkunnu Panchayat, Village: Ariyallur)



Plate-2: Mangrove patch at Thannithura (Location: 75° 56' 38.67" E 10° 42' 52.66" N, Veliyancode Panchayath, Village: Veliyancode)





Plate-3: HTL at Chettipadi (Location:  $75^{\circ} 50' 44.60''$  E  $11^{\circ} 3' 58.87''$  N, Parappanangadi Municipality, Village: Parappanangadi)



Plate-4: HTL at Parappanangadi Beach (Location:  $75^{\circ} 50' 54.06''$  E  $11^{\circ} 3' 23.03''$  N, Parappanangadi Municipality, Village: Parappanangadi)





Plate-5: Mangroves at Pariyapuram (Location: 75° 51' 56.85" E 11° 0' 50.13" N, Tanur Municipality, Village: Pariyapuram)



Plate-6: Mangrove patch at Pariyapuram (Location: 75° 52' 3.83" E 11° 0' 11.43" N, Tanur Municipality, Village: Pariyapuram)





Plate-7: HTL at Edakadappuram (Location: 75° 52' 15.67" E 10° 57' 59.69" N, Tanur Municipality, Village: Tanur)



Plate-8: Mangrove area removed at Annara, Tirur (Location: 75° 54' 25.63" E 10° 54' 44.54" N Tirur Municipality, Village: Thrikkandiyur)





Plate-9: Mangrove removed for Aquaculture at Mangattiri (Location: 75° 54' 51.61" E 10° 53' 19.90" N, Thalakkad Panchayath, Village: Thalakkad)



Plate 10: HTL at Palapetty (Location: 75° 57' 7.69" E 10° 41' 45.37" N, Perumpadappa Panchayath, Village: Perumpadappa)